

AVT-425 Vehicle Communication Controller Firmware Changelog



2704 Paldan Dr
Auburn Hills, MI 48326
248-475-9880
sales@orionmeas.com

Revision Control

Rev Date	Rev	Updated by	Description
03/31/2025	5.0.0.13	Josh Dunn	NB, ATSAM: Bug fixes

Table of Contents

Introduction3

2025-03-31: Updated Package Version 5.0.0.133

 Netburner Firmware:.....3

 ATSAM Firmware:.....3

 PIC Firmware:.....3

Introduction

The AVT-425 contains three processors: Netburner, ATSAM, and PIC. The ATSAM and PIC processors require special tools to flash, so only Netburner firmware is available for download at the Orion Measurement Solutions website:

[Documents & Downloads - Orion Measurement Solutions, Inc.](#)

To obtain the most recent firmware for the other processors, please contact Orion Measurement Solutions.

2025-03-31: Updated Package Version 5.0.0.13

Netburner Firmware:

Updated from 5.0.0.12 to 5.0.0.13

- Adds “long format only” mode to ISO15765 processing for CAN2 and CAN3

ATSAM Firmware:

Updated from 0.0.24 to 0.0.25

- Fixes bug that prevented Object 4 on CAN2 and CAN3 from receiving messages with 29-bit IDs

PIC Firmware:

No Change. Most recent version is 1.0.0.7